

小型浄化槽新旧一覧（単独）

2021/12/21作成

機種名	処理方式	人槽	発売時期 (和暦)	発売時期 (西暦)	終了時期 (和暦)	終了時期 (西暦)	マンホール枚数（樹脂製）				汚泥引き抜き (m ³)	必要風量 (L/分)	
							φ250	φ450					φ500
								478mm	492mm	502mm			
NS	変型二階腐敗タンク・平面酸化	5	S45.10	1970.10	S56.4	1981.4	3	1			1.550		
		7					3	1			1.700		
		10					3	1			2.060		
AS	全ばっ気	5	S46.9	1971.9	確認中	確認中		1			0.780		
		8						1			0.933		
		10						1			1.028		
AB	全ばっ気	5	S49.10	1974.10	S56.4	1981.4		1			0.759	40	
		8						1			0.923	40	
		10						1			1.032	40	
FS	分離ばっ気	5	S49.11	1974.11	S56.4	1981.4		2			1.066	40	
		7						2			1.329	40	
		10						2			1.617	60	
AS II	全ばっ気	5	S50.7	1975.7	S56.4	1981.4		1			0.762	40	
		8						1			0.894	40	
		10						1			0.992	40	
NB	腐敗タンク	5	S50.8	1975.8	S56.4	1981.4			2		1.510		
		7							2		1.710		
		10							2		2.010		
FS II	分離ばっ気	5	S53.1	1978.1	S56.4	1981.4		2			1.086		
		7	S53.2	1978.2				2		1.288			
		10	S53.3	1978.3				2		1.578			
AB II	全ばっ気	5	S53.4	1978.4	確認中	確認中		1			0.760		
E	分離接触ばっ気	5	S56.5	1981.5	S57.5	1982.5				2		0.758	40
		8			S56.12	1981.12				2		1.025	40
		10							2		1.203	40	
S	分離ばっ気	5	S56.5	1981.5	H3.11	1991.11				2		1.378	30~40
		6							2		1.538	30~40	
		7	S57.1	1982.1					1	1	1.754	30~40	
		8	S56.5	1981.5					1	1	1.934	40	
10					1	1	2.275	40					
E II	分離接触ばっ気	5	S57.1	1982.1	S63.12	1988.12				2		0.753	30~40
		6			H1.2	1989.2				2		0.840	30~40
		7	S57.2	1982.2	S63.12	1988.12				2		0.943	
		8	S57.1	1982.1	H11	1989				2		1.024	30~40
		10			H5.2	1993.2				2		1.200	30~40
ST	分離ばっ気	5	S57.2	1982.2	H8.3	1996.3				2		1.352	30~40
		6	S56.6	1981.6	H3.11	1991.11				2		1.550	30~40
		7	S57.2	1982.2	H8.3	1996.3				2		1.733	30~40
		8	S56.6	1981.6	H3.11	1991.11				2		1.917	40
S I	分離ばっ気	10	S61.12	1986.12	H3.7	1991.7				2		2.199	40
SP	分離ばっ気	5	S60.9	1985.9	S62.12	1987.12				2		1.227	30~40
		6	S60.10	1985.10	S63.4	1988.4				2		1.372	30~40
		7	S60.9	1985.9	S63.3	1988.3				2		1.502	30~40
EP	分離接触ばっ気	5	S63.1	1988.1	H11	1989				2		0.752	
		6								2		0.850	
		7								2		0.934	
EC	分離接触ばっ気	10	H3.2	1991.2	H11	1989				2		1.208	40

※マンホール枚数は本体のみになります。